

Safety on Toyota FCEVs



FUEL CELLS AND HYDROGEN JOINT UNDERTAKING

Vincent Mattelaer, TME

18 November 2021



Stance from Toyota







We build hydrogen fuel cell vehicles with at least the same safety level as vehicles with conventional fuels.





Lessons learnt from H2 incidents FCEVs do not release hydrogen easily. Most hydrogen incidents occur at an hydrogen installation (Industry, HRS, transport, ..)



Source: https://fch.europa.eu/sites/default/files/Assessment%20and%20lessons%20learnt%20from%20HIAD%202.0.pdf







Mirai Accidents in Europe















Safety Measures for H₂ in a FCEV







Safety Measures for H₂ in a FCV







I will come to this point more in detail later.







Hydrogen tank positioned to lessen damage







1. Ensure that hydrogen does not

Source: https://youtu.be/FgLTUbWyEa0







Rear tank internal volume = 62.4 L

Plastic liner

Carbon fiber-reinforced plastic layer (CFRP)

Glass fiber-reinforced plastic layer (GFRP)



1. Ensure that hydrogen does not

Tank designers run a load of harsh tests in laboratories

- Burst test
- Cycling test
- **Bonfire tests**
- Crush test (Powertech)
- Cold weather tests
- Gunfire test (tested@Powertech)







Photron



1. Ensure that hydrogen does not

Source: https://youtu.be/jVeagFmmwA0

1. Ensure that hydrogen does not

Safety Measures for H₂ in a FCV

2. Immediate Stoppage of H2 Floving

Safety Measures for H₂ in a FCV

3: Isolation of parts

Safety Measures for H₂ in a FCV

Hydrogen Tank

FCEV Underground Parking

FUEL CELLS AND HYDROGEN JOINT UNDERTAKING

Vincent Mattelaer, CEP/TME

18 November 2021

Underground Parking of Hydrogen Vehicles

Workshop on Safe Storage of Hydrogen

Risk of FCEV Underground Parking prohibition

French ministry of internal affairs states the following at page 23 of their covered parking safety practical guide:

"Therefore, pending further trials and feedback, it is recommended to park vehicles in uncovered spaces (roof terrace for example)."

Austrian Building Regulation: OIB-330.2-014/19 Clause 8.1

"Hydrogen and LPG vehicles are not allowed to park underground."

- >50m²
- Some other conditions

Source: https://www.oib.or.at/sites/default/files/ri chtlinie 2.2 12.04.19 0.pdf

Source: https://www.sitesecurite.com/contenu/erpps/guide 20 18 01 30 de preconisations ps.pdf

Austria

(Special fire protection concept) • Seems not to be the case for CNG

The Netherlands

Ministry of Internal affairs

Request to NEN to create a standard about fire safety and risk assessment in underground parking garages.

Dutch Institute

Current situation:

Risk that FCEVs will not be allowed to park underground

Underground Parking of Hydrogen Vehicles

Workshop on Safe Storage of Hydrogen

Root Causes for not allowing FCEVs to park underground

- Not enough information for construction engineers or fire departments
- Many (hydrogen) scientific papers are based on CNG issues. (High failure %)

Countermeasure

Detailed document or website needed for construction engineers, authorities and fire departments that explains that hydrogen vehicles are safe so they are allowed to park in underground garages or covered areas.

Hydrogen cars in parking garages

Source: https://www.ifv.nl/kennisplein/Documents/20210209-IFV- Hydrogen-cars-in-parking-garages.pdf

Vincent Mattelaer

Senior Engineer Vincent.mattelaer@toyota-europe.com

For futher information

www.fch.europa.eu www.hydrogeneurope.eu www.nerghy.eu

FUEL CELLS AND HYDROGEN JOINT UNDERTAKING

